



52 Aurora Street



- North-Facing
- Cedar Cellulose & Rotting
- Weathering & Water Damage
- Poor Density & Integrity





- Rotting

- Lack of Density, Integrity



- **Poor Paint Adherence**
- **Not White Underneath**



- **Black Mold**

- **Green Mold**





- Termite- & Ant-Consumable & Infestations

