





The rear-view windows – Second floor window was changed to a crank out style as it can be used for emergency exit from second floor to roof.
The chimney was able to be taken down to basement and this allowed the kitchen sink to be moved to face the rear yard and the casement window from driveway was traded for the double hung window in the rear. The casement window then in the first-floor rear was centered below the second-floor window.
No muntin bars on the rear elevation allows for clear view of the backyard. (Non-public face)



The rear-view windows – Second floor window was changed to a crank out style as it can be used for emergency exit from second floor to roof.
 The chimney was able to be taken down to basement and this allowed the kitchen sink to be moved to face the rear yard and the casement window from driveway was traded for the double hung window in the rear. The casement window then in the first-floor rear was centered below the second-floor window.
 No muntin bars on the rear elevation allows for clear view of the backyard. (Non-public face)

COMMUNITY DEVELOPMENT
 DEPARTMENT
 Approved
 7/26/18
 Zoning Certificate #:
 4365



NO MUNTIN BARS
 ELEVATION FOR
 BETTER VIEW
 OF REAR YARD
 THESE WINDOWS ARE
 NOT ON PUBLIC FACE


| | | |
|--------------------------|--------------|------------------|
| 29 COLLEGE ST. HUDSON O. | | |
| SCALE: 1/8"=1'-0" | APPROVED BY: | DRAWN BY: SAS |
| DATE: 7/3/18 | | REVISED |
| | | DRAWING NUMBER 2 |

OHIO
HUDSON
 COMMUNITY DEVELOPMENT
 DEPARTMENT


Approved

7/26/18

Zoning Certificate #:
 4365



SECOND FLOOR
 424 SQ. FT.



FIRST FLOOR
 942 SQ. FT.

WINDOW EXCHANGED



1366 TOTAL SQ. FT.

| | | |
|--------------------------|--------------|----------------|
| 29 COLLEGE ST. HUDSON O. | | |
| SCALE: 1/4" = 1'-0" | APPROVED BY: | DRAWN BY: BMS |
| DATE: 7/3/18 | | REVISED: |
| | | DRAWING NUMBER |
| | | 1 |



The front window headers – (As shown in photos) Once the aluminum siding was removed it was found that the old window headers were not straight and the change was made to copy the old window headers for historical accuracy. The old photos make it hard to see the windows but the door is visible in the old photos with the header shape.







1 2

