





Existing



Proposed

Scope of Work

- Repair existing posts/swinging gates.
- Add two (2) sections of trellis to each side, wood construction. 4' at highest point, 3' at lowest point.