




CAMPBELL &  
ASSOCIATES, INC.  
Surveying - Engineering

(330) 945-4117  
Fax: (330) 945-4140  
1923 Bailey Road  
Suite A  
Cuyahoga Falls, OH 442  
<http://www.campbellsurvey.com>

MORTGAGE LOCATION SURVEY




Arbor  
60"Wx86"Hx25"D

Lattice  
6'Hx24'L

33'2" to property line



Privacy Lattice: — (blue line)  
Arbor: — (red line)



Address: 130 Aurora Street

Allotment: City

State of Ohio, County of Summit

Plot Book: 1, Page 34

Client Order No. 200805100

C & A Order No.  
CF112775

City of Hudson

Date: May 22, 2008

New Owner: Scott A. Hornick and Laura A. Hornick

Present Owner: Robert J. Deubery and Lori Deubery


This is to certify to **Bank Mortgage Inc and/or Dynamic Title Agency**

that a visual inspection of the property and buildings shown (if any) has been made and there are no apparent encroachments or visible easements unless otherwise shown. This service was not performed for the purpose of establishing boundary lines, and is not to be used for that purpose.


This Mortgage Location Survey has been prepared in accordance with Chapter 4733-36, Ohio Administrative Code, and is not a boundary survey pursuant to Chapter 4733-37, Ohio Administrative Code

*James P. Yurkschatt*  
James P. Yurkschatt - Reg. Surveyor No. 7809

# ELEVATION



## Materials



4 foot x 8 foot Cedar Lattice



**Laura Honnold**

[Remove Comment](#) • Oct 25, 2022 at 11:12 am

We plan to use the lattice in the photo of the 4'x8' section.



**Post Caps for 4x4 Cedar Posts**

P

Cedar  
Arbor:  
60"W  
86"H  
25"D







