

SR 91 & SR 303 Curb Radius Review

Existing Intersection



Truck Turning over Curb Ramps


- Larger vehicles including busses and trucks have difficultly making turning movements at intersection due to tight curb radii.
- Most common type of trucks using intersection:



Example Photos of issue:



Truck Turning over Curb Ramps



Potential Improvements

Full Design to Accommodate Large Trucks




High Cost

Relocation of existing signal poles, lights and other infrastructure

Large Traffic Impacts

Potential Improvements

Smaller Adjustments to Existing Curb Radius



Trucks will still run over curb ramps

E. Case Dr, W. Case Dr, Hartford Rd. and Milford Rd. Speed & Traffic Volumes

Road	Study Year	Value	Avg Speed (mph)	85th %ile Speed (mph)
E. Case Dr.	May, 2003	448	27	30
E. Case Dr.	May, 2023	629	24	29
W. Case Dr.	May, 2003	216	22	24.8
W. Case Dr.	No Recent Count Data Available			
Hartford Dr.	August, 2003	146	25	29.9
Hartford Dr.	No Recent Count Data Available			
Milford Rd.	2005	3,249*	30.5	35.5
Milford Rd.	July, 2024	6,516	26	30

^{*}Prior to Veterans Way Construction