



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

1. No.		4. Present Name(s)	
2. County Summit		Residence, G. D. Davis	
3. Location of Negatives HHA 32-23		5. Other Name(s)	
6. Specific Location 90 Oviatt Street		16. Thematic Category D	28. No. of Stories 1
7. City or Town If Rural, Township & Vicinity Hudson		17. Date(s) or Period c. 1940	29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
8. Site Plan with North Arrow 		18. Style or Design Minimal Traditional	30. Foundation Material brick faced
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference 17 465530 4565671		19. Architect or Engineer Geo Burroughs	31. Wall Construction wood frame
10. Site <input type="checkbox"/> Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>		20. Contractor or Builder	32. Roof Type & Material gable - asph shingle
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		21. Original Use, if apparent residence	33. No. of Bays Front 6 Side 3
12. Is it Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use residence	34. Wall Treatment beveled siding
13. Part of Estab. Hist. Dist.? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>	35. Plan Shape rect
14. District Potent'l? Yes <input type="checkbox"/> No <input type="checkbox"/>		24. Owner's Name & Address, If known G. D. Davis 90 Oviatt Street Hudson 44236	36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>
15. Name of Established District Hudson Local Historic District		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	37. Condition Interior _____ Exterior <u>good</u>
16. Further Description of Important Features Center gable; dropped shed roof porch with slender square supports; four 4/4 windows under porch roof, two 8/12 under centered gable; double chimney, south side.		26. Local Contact Person or Organization Hudson Heritage Association	38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
17. History and Significance		27. Other Surveys in Which Included	39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
18. Description of Environment and Outbuildings Detached garage; residential area, many old houses.		28. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	40. Distance from and Frontage on Road 45' <u>50'</u>
19. Sources of Information Summit County Tax Assessment records Personal inspection		29. Prepared by L Newkirk, F Barlow	30. Organization HHA
		31. Date	32. Revision Date(s)

1. No.
2. County
Summit
3. Precinct (county)
Residence, G. D. Davis
4. City (county)
Hudson

Site Plan





A

2. Detailed Explanation of Project *

Single window at rear of garage. Rotting window casement removed and closed off. All rotted wood replaced and siding was matched to existing 6" Dutch lap wood. Outside was primed and painted to match existing garage.



B

Detailed Explanation of Project *

Board damage, second floor, North side of dwelling below windows. Damage occurred from roof replacement in 2015 and flashing was extended for better protection. Replaced boards with like 8' clapboard cedar siding and prime and paint.

