



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

1. No.		4. Present Name(s) Residence, B. Brucker		5. Other Name(s)	
2. County Summit					
3. Location of Negatives HHA 51-37					
6. Specific Location E 104 Streetsboro Street, at Oviatt		16. Thematic Category C		28. No. of Stories 2	
7. City or Town If Rural, Township & Vicinity Hudson		17. Date(s) or Period c. 1875		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
8. Site Plan with North Arrow 		18. Style or Design not determined		30. Foundation Material sandstone/tile/cement b	
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference 17 463567 4565237		19. Architect or Engineer		31. Wall Construction wood frame	
10. Site <input type="checkbox"/> Structure <input type="checkbox"/> Building <input checked="" type="checkbox"/> Object <input type="checkbox"/>		20. Contractor or Builder		32. Roof Type & Material x-gable, asph shingle	
11. National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		21. Original Use, if apparent residence		33. No. of Bays Front 2 Side 3	
12. Is it Eligible? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		22. Present Use residence		34. Wall Treatment beveled siding	
13. Part of Estab. Yes <input checked="" type="checkbox"/> Hist. Dist.? No <input type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		35. Plan Shape Latin Cross	
14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		24. Owner's Name & Address, if known B. Brucker 104 Streetsboro St Hudson 44236		36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/>	
15. Name of Established District Hudson Local Historic District		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		37. Condition Interior _____ Exterior good	
16. Further Description of Important Features Victorian accents; wraparound porch, columns, endboards, boxed cornice, brackets, pedimented window lintels, single stack brick chimney. Windows slide into walls. Two additions at rear, 1 1/2 and 1 story; addition to west at rear.		26. Local Contact Person or Organization Hudson Heritage Association		38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
17. History and Significance First owner Fitch. Later owners L. L. Roby, T. L. Robinson. 51-37		27. Other Surveys in Which Included		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
18. Description of Environment and Outbuildings On heavily traveled S. R. 303, in area of historic houses. Detached garage.		28. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		40. Distance from and Frontage on Road 48' 112'	
19. Sources of Information Summit County Tax Assessment records. HHA Architectural Survey & Research Comm. files Personal inspection		29. Prepared by L Newkirk, F Barlow		41. Organization HHA	
		30. Date		42. Revision Date(s)	

4' decorative wood fence gate



4' decorative wood fence

4' wood stockade fence (existing neighbor's fence)

SITE PLAN
1" = 20'-0"



Proposed Fence: 4' decorative, wood fence













Existing
Neighbor's
fence





Existing
Neighbor's
fence



