



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No.</p> <p>2. County SUMMIT</p> <p>3. Location of Negatives HHA 49-35</p>	<p>4. Present Name(s) Residence, Gretchen Walker</p> <p>5. Other Name(s)</p>	1. No.				
<p>6. Specific Location 126 Aurora Street</p>	<p>16. Thematic Category D</p> <p>17. Date(s) or Period c. 1930</p>	<p>28. No. of Stories 1</p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p>	2. County SUMMIT			
<p>7. City or Town Hudson <small>If Rural, Township & Vicinity</small></p>	<p>18. Style or Design Colonial Revival</p>	<p>30. Foundation Material brick faced</p> <p>31. Wall Construction wood frame</p>	4. Present Name(s) Residence, G. Walker			
<p>8. Site Plan with North Arrow</p> 	<p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent residence</p> <p>22. Present Use residence</p>	<p>32. Roof Type & Material gable, asph shingle</p> <p>33. No. of Bays Front 4 Side 3</p> <p>34. Wall Treatment alum siding</p> <p>35. Plan Shape rect/wing</p>	5. Other Name(s)			
<p>9. Coordinates</p> <p>Lat. _____ Long. _____</p> <p>U.T.M. Reference</p> <table border="1" style="width:100%; text-align: center;"> <tr> <td>17</td><td>463893</td><td>4565739</td> </tr> </table> <p>Zone _____ Easting _____ Northing _____</p>	17	463893	4565739	<p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known Gretchen Walker 126 Aurora Hudson, Ohio 44236</p>	<p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior _____ Exterior <u>excellent</u></p>	
17	463893	4565739				
<p>10. Site <input type="checkbox"/> Structure <input type="checkbox"/> Building <input checked="" type="checkbox"/> Object <input type="checkbox"/></p> <p>11. National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input type="checkbox"/></p>	<p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization Hudson Heritage Association</p> <p>27. Other Surveys in Which Included</p>	<p>38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road 42' 71'</p>				
<p>15. Name of Established District Hudson Local Historic District</p>	<p>42. Further Description of Important Features NW corner porch, round pillar supports; porch roof overlapping front gable; long, narrow triple windows on front gable section, 4/6 double-hung; gable dormer with casement windows on side gable; 6/6 double-hung windows on side gable.</p>	<p>Photo</p>				
<p>43. History and Significance</p>						
<p>44. Description of Environment and Outbuildings Detached garage. Residential street of historic houses, heavily traveled.</p>						
<p>45. Sources of Information Summit County Tax Assessment Records Personal inspection.</p>	<p>46. Prepared by L. Newkirk, F. Barlow</p> <p>47. Organization HHA</p>	<p>48. Date</p> <p>49. Revision Date(s)</p>				

Site Plan





DOOR

7"

3" Sandstone Landing

7"

12" STEP

4x8x2 BRICK & MORTAR

7" RISE

PAVER SAND 2"
PAVER STONE 2"

GROUND


4" 1/2 Aggregate (STONE)

48"

48"

60"

3" SANDSTONE LANDING



Step Detail

- Measurements: 20w x 48ht
- Construction: Solid wood
- Finish: Natural interior and white exterior finish
- Trim: Using Aluminum J-Channel to integrate with existing Aluminum siding.
- Style: This is a fixed window with 8 lite grid (does not open)
- Being salvaged from existing 3 bay casement



- Measurements: 36w x 38ht
- Construction: Solid wood
- Finish: Natural interior and exterior finish (will paint exterior white to match house)
- Trim: Using Aluminum J-Channel to integrate with existing Aluminum siding.
- Style: This is a 2 bay crank casement window with 8 lite grids (1 right and 1 left)
- This window is currently still installed above our sink and left in place after the addition was added.
- It will replace the existing casement to allow space underneath for cabinets and sink.

Relocate Window


2.

1.

4.

Door to be removed and relocated on opposite side of addition





#2

#1

#4

Measure details

Door (#1)

- It is existing door that was installed in the 1930s.
- Mfg is unknown.
- Measurements: 32w x 80ht
- Construction: Solid Wood
- Finish: Natural interior and White Paint Exterior
- Trim: Using Aluminum J-Channel to integrate with existing Aluminum siding.
- Style: 9-lite grid Colonial

Window (#2)

- It is an existing window that was installed in the 1930s.
- Mfg is unknown
- Measurements: 20w x 48ht
- Construction: Solid wood
- Finish: Natural interior and white exterior finish
- Trim: Using Aluminum J-Channel to integrate with existing Aluminum siding.
- Style: This is a fixed window with 8 lite grid (does not open)
- Being salvaged from existing 3 bay casement


Window (#4)

- It is an existing window that was installed in the 1930s.
- Mfg is unknown
- Measurements: 36w x 38ht
- Construction: Solid wood
- Finish: Natural interior and exterior finish (will paint exterior white to match house)
- Trim: Using Aluminum J-Channel to integrate with existing Aluminum siding.
- Style: This is a 2 bay crank casement window with 8 lite grids (1 right and 1 left)
- This window is currently still installed above our sink and left in place after the addition was added.
- It will replace the existing casement to allow space underneath for cabinets and sink.











One Twenty Six



