



OHIO HISTORIC INVENTORY

1. No.		4. Present Name(s) Residence, Sheldon Schweikert	
2. County Summit		5. Other Name(s)	
3. Location of Negatives HSA 32-25			
6. Specific Location 19 Oviatt Street		16. Thematic Category C	
		17. Date(s) or Period 1881	
7. City or Town If Rural, Township & Vicinity Hudson		18. Style or Design not determined	
8. Site Plan with North Arrow 		19. Architect or Engineer	
		20. Contractor or Builder	
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference 17 463576 4565328		21. Original Use, if apparent residence	
		22. Present Use residence	
10. Zone Easting Northing Site <input type="checkbox"/> Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>	
		24. Owner's Name & Address, if known Sheldon Schweikert 19 Oviatt Street Hudson 44236	
11. National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
12. Is It Eligible? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		26. Local Contact Person or Organization Hudson Heritage Association	
13. Part of Estab. Hist. Dist.? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		27. Other Surveys in Which Included	
14. District Potent'l? Yes <input type="checkbox"/> No <input type="checkbox"/>		38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
15. Name of Established District Hudson Local Historic District		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
42. Further Description of Important Features Center chimney; wraparound porch, partially enclosed to form entrance, brick pillar supports extending to ground, spindlework balustrade; 12 pane entry door with sidelights; single pane double-hung windows.		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		41. Distance from and Frontage on Road 28' 60'	
43. History and Significance Ralph Miller was the first owner, a baker who shared the premises at 140 North Main Street with his brother George, a butcher. They were burned out in the 1892 fire, as was a third brother, Sebastian Miller, a shoe merchant.			
44. Description of Environment and Outbuildings 1913 detached garage. Residential street, many old houses.			
45. Sources of Information Summit County Tax Assessment records Personal inspection		46. Prepared by L Newkirk, F Barlow	
		47. Organization HSA	
		48. Date	
		49. Revision Date(s)	





N GYMAT ST

18

19

LANDMARK[®]

DESIGNER ROOFING SHINGLES

Landmark, shown in Weathered Wood

A Classic Original

Landmark's dual-layered construction provides depth and dimension, along with extra protection from the elements. Widest array of colors in the industry.

- **NAILTRAK wider nailing area**
for a more accurate installation
- **Lifetime limited warranty**
- **10-year SureStart protection**
Includes materials and labor costs
- **STREAKFighter[®] 10-year algae resistance**
- **15-year 110 MPH wind warranty**
Upgrade to 130 MPH available

CertainTeed products are tested to ensure the highest quality and comply with the following industry standards:

Fire Resistance:

- UL Class A
- UL certified to meet ASTM D3018 Type 1

Wind Resistance:

- UL certified to meet ASTM D3018 Type 1
- ASTM D3161 Class F

Tear Resistance:

- UL certified to meet ASTM D3462
- CSA standard A123.5

Wind Driven Rain Resistance:

- Miami-Dade Product Control Acceptance

Acceptance Quality Standards:

- ICC-ES-ESR-1389 & ESR-3537











