








NEW 36" ENTRY
DOOR

NEW BRICK VENEER TO
MATCH AS CLOSE AS POSSIBLE

NEW FINISHED ELEVATION

$\frac{1}{4} = 1'$

JEFF & LAURIE CSUY
82 AURORA ST
HUDSON, OH 44236




CROSS SECTION

N.T.S.

JEFF & LAURIE CSUY
82 AURORA ST
HUDSON, OH 44236

Options for new man door










OHIO HISTORIC INVENTORY

1. No. 2. Gr <u>Summit</u> 3. Location of Negatives <u>29-20</u> <u>HHA 30-4</u>	4. Present Name(s) <u>Residence, Louise Stevenson</u> 5. Other Name(s)	1. No.	
6. Specific Location <u>82 Aurora Street</u>	16. Thematic Category 17. Date(s) or Period <u>C. 1920</u>	28. No. of Stories <u>2</u> 29. Basement? Yes ☒ No ☐	2. County <u>Summit</u>
7. City or Town If Rural, Township & Vicinity <u>Hudson</u> 8. Site Plan with North Arrow 	18. Style or Design <u>Colonial Revival</u> 19. Architect or Engineer 20. Contractor or Builder 21. Original Use, if apparent <u>residence</u> 22. Present Use <u>residence</u> 23. Ownership Public ☐ Private ☒ 24. Owner's Name & Address, if known <u>Louise Stevenson</u> <u>82 Aurora Street</u> <u>Hudson 44236</u>	30. Foundation Material <u>concrete block, brick</u> 31. Wall Construction <u>wood frame</u> 32. Roof Type & Material <u>gable -slate</u> 33. No. of Bays Front <u>5</u> Side <u>4</u> 34. Wall Treatment <u>brick</u> 35. Plan Shape <u>rect /wing</u> 36. Changes (Explain in #42) Addition ☐ Altered ☐ Moved ☐ 37. Condition Interior Exterior <u>excellent</u>	4. Present Name(s) <u>Residence, L. Stevenson</u>
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference <u>17 463738 4565637</u> 10. Site ☐ Structure ☐ Building ☒ Object ☐ 11. On National Register? Yes ☐ No ☒ 12. Is It Eligible? Yes ☐ No ☒ 13. Part of Estab. Hist. Dist.? Yes ☒ No ☐ 14. District Potent'l? Yes ☒ No ☐ 15. Name of Established District <u>Hudson Local Historic District</u>	25. Open to Public? Yes ☐ No ☒ 26. Local Contact Person or Organization <u>Hudson Heritage Association</u> 27. Other Surveys in Which Included	38. Preservation Underway? Yes ☒ No ☐ 39. Endangered? By What? Yes ☐ No ☒ 40. Visible from Public Road? Yes ☒ No ☐ 41. Distance from and Frontage on Road <u>30'</u>	5. Other Name(s)
42. Further Description of Important Features <u>Basement garage. Pedimented portico entry; pent roof over bay window on front facade; 2/2 double hung windows.</u>		Photo	
43. History and Significance <u>Charles Jerosch, 1929.</u> <u>Built on the original site of the Jesse Dickinson house, now at 80 Oviatt Street.</u>			
44. Description of Environment and Outbuildings <u>Residential street of historic homes, heavily traveled.</u>			
45. Sources of Information <u>Summit County Tax Assessment records</u> <u>Personal inspection</u>		46. Prepared by <u>L Newkirk, F. Barlow</u> 47. Organization <u>HHA</u> 48. Date 49. Revision Date(s)	