




2115 EAST STREETSBORO, HUDSON, OHIO

# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
Ohio Historical Center  
Columbus, Ohio 43211

1. No.		4. Present Name(s) Residence, F. Trotter	
2. County Summit		5. Other Name(s)	
3. Location of Negatives HHA 11-17,18			
6. Specific Location 2115 Streetsboro Street		16. Thematic Category C	
		17. Date(s) or Period c. 1893	
7. City or Town If Rural, Township & Vicinity Hudson		18. Style or Design not determined	
8. Site Plan with North Arrow 		19. Architect or Engineer	
		20. Contractor or Builder	
9. Coordinates Lat. _____ Long. _____ U.T.M. Reference 17 464884 4565288		21. Original Use, if apparent	
		22. Present Use residence	
10. Zone _____ Easting _____ Northing _____ Site <input type="checkbox"/> Structure <input type="checkbox"/> Building <input checked="" type="checkbox"/> Object <input type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>	
		24. Owner's Name & Address, if known F. Trotter 2115 Streetsboro St. Hudson 44236	
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
12. Is it Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/>		26. Local Contact Person or Organization Hudson Heritage Association	
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		27. Other Surveys in Which Included	
14. District Potent'l? Yes <input type="checkbox"/> No <input type="checkbox"/>		28. No. of Stories 2	
15. Name of Established District		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
42. Further Description of Important Features Original house was present kitchen and living room. Owner says very poorly built, with varied construction methods; thinks it may be several houses joined. Stone supported porch pillars; leaded glass in front window; west side bay is two story tower; small gables in front and side; porch added.		30. Foundation Material sandstone block	
		31. Wall Construction wood frame	
43. History and Significance Former owner F. Juzek, Strongsville, Ohio. 11-17,18		32. Roof Type & Material gable - tar	
		33. No. of Bays Front 3 Side 3	
44. Description of Environment and Outbuildings Detached garage.		34. Wall Treatment shingles	
		35. Plan Shape rect	
45. Sources of Information Summit County Tax Assessment records Personal inspection, interview with owner		36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/>	
		37. Condition Interior _____ Exterior <u>door</u>	
46. Prepared by J Caccamo, D Cesaratto		38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
47. Organization HHA		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		41. Distance from and Frontage on Road 55' 262'	
48. Date		49. Revision Date(s)	

Summit Residence, F. Trotter





## 2115 STREETSBORO ROAD

Cross gabled and wood shingled, c. 1893,  
with a hipped porch roof and paired win-  
dows. 1920s garage.



328





The main structure is a small, red-painted wooden shed with a gabled roof. The paint is significantly peeling, revealing the underlying wood. It features a single window with a red frame and a grey downspout on the right side. The shed is situated on a wooden deck.

A rectangular, grey-painted wooden planter box with four legs, positioned in front of the shed.

A concrete patio area to the right of the shed, featuring a wooden table and two wicker chairs.

A dark-colored car, possibly a Honda, parked on a gravel area to the right of the shed.

A wooden deck area to the left of the shed, with a black metal frame structure and some outdoor furniture.

A small, white gazebo with a red roof, located in the background on the left side.

A larger, white house with a grey roof and green shutters, visible in the background on the right side.







